



Part Number: 113N2800-95SP

Part Description: Inboard Trailing Edge  
AFT Flap Assemblies

## Specifications

|                              |                              |
|------------------------------|------------------------------|
| Product Families:            | Flight Controls and Surfaces |
| Product Group:               | Flight Spoilers              |
| Part Number                  | 113N2800-95SP                |
| Root Part Number             | 113N2800-95SP                |
| ATA Chapter 2 Digit          | 57                           |
| ATA Chapter 4 Digit          | 57-53                        |
| ATA Chapter 6 Digit          | 57-53-45                     |
| MFR / Manufacture -CAGE Code | Boeing                       |
| Application                  | B757                         |

## Repair

|                      |   |
|----------------------|---|
| Part Number          | 113N2800-95SP                             |
| Description          | Inboard Trailing Edge AFT Flap Assemblies |
| Repair Manual- CMM   | CMM                                       |
| Bench Check & Advise | Yes                                       |
| Repair               | Yes                                       |
| Overhaul             | Yes                                       |
| Repair Facility      | Miami Lakes                               |

## Logistics

|             |   |
|-------------|---|
| Part Number | 113N2800-95SP                             |
| Description | Inboard Trailing Edge AFT Flap Assemblies |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737