



Part Number: 114T0201-47

Part Description: Thermal Anti-icing duct seal door assembly

## Specifications

|                              |             |
|------------------------------|-------------|
| Product Families:            | Structures  |
| Product Group:               | Doors       |
| Part Number                  | 114T0201-47 |
| Root Part Number             | 114T0201-47 |
| ATA Chapter 2 Digit          | 57          |
| ATA Chapter 4 Digit          | 57-41       |
| ATA Chapter 6 Digit          | 57-41-10    |
| MFR / Manufacture -CAGE Code | Boeing      |
| Application                  | B757        |

## Repair

|                      |  |
|----------------------|--|
| Part Number          | 114T0201-47                                |
| Description          | Thermal Anti-icing duct seal door assembly |
| Repair Manual- CMM   | CMM  |
| Bench Check & Advise | Yes  |
| Repair               | Yes  |
| Overhaul             | Yes  |
| Repair Facility      | Miami Lakes                                |

## Logistics

|             |  |
|-------------|--|
| Part Number | 114T0201-47                                |
| Description | Thermal Anti-icing duct seal door assembly |

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737