



Part Number: 1375M39G10

Part Description: Forward Fan Case  
Outer Liner Segments

## Specifications

Product Families:	Nacelles
Product Group:	Fan Cowl
Part Number	1375M39G10
Root Part Number	1375M39GXX
ATA Chapter 2 Digit	72
ATA Chapter 4 Digit	72-22
ATA Chapter 6 Digit	72-22-02
MFR / Manufacture -CAGE Code	Boeing
Application	CF6 - 50 & 80

## Repair

Part Number	1375M39G10
Description	Forward Fan Case Outer Liner Segments
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Repair Facility	Hialeah

## Logistics

Part Number	1375M39G10
Description	Forward Fan Case Outer Liner Segments

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

**630 Aerospace where quality is built in not inspected.**



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737