



Part Number: 238W0904-515

Part Description: Fan Case Left Side Harness

Specifications

Product Families:	Harnesses
Product Group:	Engine Systems
Part Number	238W0904-515
Root Part Number	238W0904-515
ATA Chapter 2 Digit	71
ATA Chapter 4 Digit	71-50
ATA Chapter 6 Digit	71-50-00
MFR / Manufacture -CAGE Code	Rohr
Application	CFM56

Repair

Part Number	238W0904-515
Description	Fan Case Left Side Harness
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Hialeah

Logistics

Part Number	238W0904-515
Description	Fan Case Left Side Harness

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737